

AD-A156 254


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
MOLCOTT DAM (VT 00179) (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JUN 80


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

PHOTOGRAPH THIS SHEET

AD-A156 254

DTIC ACCESSION NUMBER

LEVEL

INVENTORY

WOLCOTT DAM VT 00179

DOCUMENT IDENTIFICATION
JUNE 1980

This document has been approved
for public release and sale; its
distribution is unlimited.

DISTRIBUTION STATEMENT

ACCESSION FOR

NTIS GRA&I ☒

DTIC TAB ☐

UNANNOUNCED ☐

JUSTIFICATION

BY

DISTRIBUTION /

AVAILABILITY CODES

DIST

AVAIL AND/OR SPECIAL

A-1

DISTRIBUTION STAMP

DTIC
ELECT
JUL 03 1985
S E D

DATE ACCESSIONED

DATE RETURNED

85 7 03 088

DATE RECEIVED IN DTIC

REGISTERED OR CERTIFIED NO.

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDAC

AD-A156 254

RICHELIEU RIVER BASIN
WOLCOTT , VERMONT

WOLCOTT DAM
VT 00179

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

JUNE, 1980

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER VT 00179	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Wolcott Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE June 1980
		13. NUMBER OF PAGES 45
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		18a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Richelieu River Basin Wolcott VT. Lanoille River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a reinforced concrete gravity structure about 384 ft. long and 51.87 ft. high. The dam is in fair condition. Structural and mechanical condition is good. It is intermediate in size with a high hazard potential. There are various recommendations and remedial measures which must be undertaken by the owner.		

WOLCOTT DAM

VT 00179

RICHELIEU RIVER BASIN

WOLCOTT, VERMONT

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

LETTER OF TRANSMITTAL
FROM THE CORPS OF ENGINEERS TO THE STATE
TO BE SUPPLIED BY THE CORPS OF ENGINEERS

BRIEF ASSESSMENT
PHASE I INSPECTION REPORT
NATIONAL PROGRAM OF INSPECTION OF DAMS

Identification Number:	VT 00179
Name of Dam:	WOLCOTT DAM
Town:	WOLCOTT
County and State:	LAMOILLE COUNTY, VERMONT
Stream:	LAMOILLE RIVER
Date of Inspection:	MAY 6,7,8, 1980


The dam, constructed about 1920, is a reinforced concrete gravity structure approximately 384 feet long and 51.87 feet in height. The upstream face is vertical, the downstream face is typically sloped at 7-5/8 horizontal to 12 vertical. The top is flat and of varying width except for the divided spillway, which has an ogee crest. The dam includes a 120 foot long spillway section on the right side, a central sluiceway pier with manually operated sluice gate controlling a 6 foot diameter low level outlet at the dam base, a 66 foot long spillway section to the left of the sluiceway pier, and a left abutment section with an intake structure and controls for two 6 foot diameter penstocks for power generation. All gates and controls are reported operable. Both spillway sections are at equal elevations. A 16 foot high concrete dike exists on the right bank of the flowage approximately 150 yards upstream of the main dam.


The dam is on the Lamoille River approximately 40 miles upstream from Lake Champlain. It was constructed and is presently used for power generation. The reservoir is 2500 feet long with a surface area of about 12 acres. Normal storage capacity is estimated at 258 acre-feet.

Based upon the visual inspection and the review of available data regarding this facility, the dam is considered to be in FAIR condition. This assessment is based primarily upon concerns regarding spillway hydraulic capacity and effect of flashboards on dam stability. Structural and mechanical condition is good.

In accordance with the Corps of Engineers Guidelines and the size (INTERMEDIATE) and hazard (HIGH) of this dam, the Test Flood is equivalent to the Probable Maximum Flood (PMF). Peak inflow to the Wolcott Dam reservoir is 117,863 cfs; routed Test Flood outflow from the dam is 114,800 cfs with the water elevation 10.6 feet over the dam crest. The spillway capacity is 18,672 cfs, which is equivalent to 16% of the routed Test Flood outflow from the dam.

It is recommended that the owner engage a qualified, registered engineer to assess the significance of the seepage occurring on the downstream faces of the dam and the dike, to determine the effect of the currently-used flash-board system on dam stability, and to perform a detailed hydrologic and hydraulic investigation to further assess the need for and means to increase the project discharge capacity. It is also recommended that the moss, trees and debris on the face and within 10 feet of the toe of the existing dike be removed. These and remedial measures which are discussed in Section 7 should be instituted within one year of the owner's receipt of this report.


Stephen D. Murray, P.E.
Project Manager
James W. Sewall Company



This Phase I Inspection Report on _____ Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division

FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division

SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:

JOE B. FRYAR
Chief, Engineering Division

THIS SHEET TO BE FURNISHED BY THE CORPS OF ENGINEERS

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

REPORT

1. PROJECT INFORMATION	1-1
1.1 General	1-1
a. Authority	1-1
b. Purpose of Inspection Program	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-1
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-2
g. Purpose of Dam	1-2
h. Design and Construction History	1-3
i. Normal Operation Procedures	1-3
1.3 Pertinent Data	1-3
a. Drainage Area	1-3
b. Discharge at Dam Site	1-3
c. Elevation	1-4
d. Reservoir	1-4
e. Storage	1-4
f. Reservoir Surface	1-5
g. Dam - Dike	1-5
h. Diversion and Regulating Tunnel	1-5
i. Spillway	1-5
j. Regulating Outlets	1-6

<u>Section</u>	<u>Page</u>
2. ENGINEERING DATA	2-1
2.1 Design	2-1
a. Available Data	2-1
b. Design Features	2-1
c. Design Data	2-1
2.2 Construction	2-1
a. Available Data	2-1
b. Construction Considerations	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	3-1
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-1
d. Reservoir Area	3-2
e. Downstream Channel	3-2
3.2 Evaluation	3-3
4. OPERATIONAL AND MAINTENANCE PROCEDURES	4-1
4.1 Operational Procedures	4-1
a. General	4-1
b. Warning System	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	5-1
5.1 General	5-1

SECTION 4: OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 OPERATIONAL PROCEDURES

a. General - Normal procedure is to generate power continuously at times of high water, curtailing evening operation to maintain the pool elevation when the river flow is less adequate. There is an occasional drawdown of the pool for maintenance purposes.

b. Warning System - There is no formal warning system, but an operator is on duty when the station is operating and is able to report any unusual occurrences.

4.2 MAINTENANCE PROCEDURES

a. General - Routine maintenance such as lubrication and equipment cleaning is performed under the direction of Mr. William Fee, Superintendent for the Village of Hardwick on a scheduled basis by on-site operators. Major maintenance is performed on an "as necessary" basis.

b. Operating Facilities - The operating facilities including gates for the penstocks, motorized rake for the trashrack and the sluice gate are in generally good condition, indicative of adequate maintenance.

4.3 EVALUATION

The operation and maintenance procedures at this dam are adequate to ensure that all problems encountered can be remedied within a reasonable period of time. The owner should establish a written warning system to follow in the event of flood flow conditions or imminent dam failure.

3.2 EVALUATION

On the basis of visual examination the dam is considered to be in fair condition.

Minor seepage was noted at two points on the dam face and at two points on the dike face. These are not considered indicative of any current structural problem.

Openings for flashboard attachment were incorporated into the dam renovation work performed in 1948. It is unknown what provision, if any, was made in the original dam design for flashboard attachment.

The reinforced concrete ice protector enclosing the sluice gate supports has eroded to the extent that ice or debris interference with sluice gate operation is possible.

A hairline crack is evident at the bend in the left abutment wall. This is not considered structurally significant at this time.

Moss and debris have accumulated on the outside of the dike wall in sufficient quantity to make observation of concrete condition and seepage sources difficult.

Outlet

A low level reservoir outlet is located in the approximate center of the dam as shown in Photos 2 and 3. Access is via a steel truss footbridge from the left abutment, in good condition but exhibiting moderate rusting. The outlet is sufficiently low to relieve hydrostatic pressure on the dam and to facilitate dam repair. The gear operator for the sluice gate on the outlet is shown in Photo 8. This equipment appears in good condition and is reported operable. There is moderate erosion, visible at the extreme right of Photo 7, at the water line of the concrete ice protector enclosing the sluice gate supports. The outlet is a 6 foot diameter steel lined conduit about 10 feet above the bedrock foundation.

Concrete Dike

About 150 yards upstream of the dam site, on the right side of the reservoir, is a concrete dike 125 feet long, 3 feet across the top and 16 feet high at its highest point. The dike prevents by-passing of the dam by overflow from the reservoir via a gully through which the Lamoille Valley Railroad tracks pass. It appears in good structural condition with some spalling of the surface concrete.

The dike is shown in Photos 9 and 10. On May 8 the reservoir water surface was 5 feet below the top of the dike.

There is some very minor clear seepage at the base of the dike near its downstream end and slight seepage from a 2 inch plugged pipe, of unknown function, in the dike. The outside face is partially moss-covered, and a few hardwood saplings have taken root in the organic debris on and at the foot of the dike. In the gully below the dike is a mixture of small hardwood trees, 2 to 6 inches in diameter.

d. Reservoir Area - The reservoir is long and relatively narrow, as is typical for a run-of-the-river dam. The reservoir banks are wooded, with no indications of instability in the vicinity of the dam.

e. Downstream Channel - The downstream channel below the spillway and outlet works, shown in Photos 11 and 12, is moderately steep, clear, and free of obstructions. Bedrock is exposed along the entire channel. Downstream channel banks are typically ledgy and forested with mixed growth as shown in Photos 12 and 13. Approximately 3000 feet downstream of the dam, Vermont Route 15 is carried over the river by the pair of highway bridges with an island between as shown in Photo 13. Within the next 3000 feet are three more bridges spanning the river - one railroad and two roadway. Development along most of the channel bank is sparse, and buildings are considerably above channel level. The Town of Wolcott, about 6000 feet downstream of the dam, is a relatively congested area with several buildings at low elevations with respect to the river.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General - At the time of inspection on May 6, 1980, water was flowing through the penstocks for power generation and the water level in the reservoir had been drawn down approximately 8 inches below spillway elevation, providing an opportunity to view the downstream spillway face as shown in Photos 1, 2 and 3. Heavy showers during the night produced a significant increase in river flow such that during continued inspection on May 7 and 8 the reservoir level was about 3 inches above the 30 inch high flashboards. The weather was cloudy and mild on May 6, cooler with showers on May 7, clearing on May 8. The general condition of this dam is fair.

b. Dam - The dam is a concrete gravity section founded on bedrock as shown in the panoramic view of the downstream face - Photos 1, 2, and 3. An intake control structure and gate house is located on the left abutment as shown in Photo 3. The structure houses a mechanically cleaned trash rack and control gates for two 6 foot diameter penstocks which convey water to the power plant approximately 175 yards downstream of the dam as shown in Photo 4. The trash rack cleaner is electrically powered; the gate operators are manual rack and pinion type. This equipment appears in good condition and is reported operable. The wood frame gate house is in good condition; the electrical system is antiquated and in fair condition. Concrete components of the dam appear in good condition.

Efflorescence and minor spalling, visible in Photo 3, were noted on the downstream face of the intake control structure, and a hairline crack was noted on the upstream face of the left abutment wall at the corner near the center of Photo 7. Photo 5 shows the downstream contact of the concrete dam and the right abutment bedrock. The minor leakage visible on the lower surface of the concrete is clear and occurs at points where an interior construction joint drainage system terminates. The drainage system was installed behind a new concrete facing placed on the existing dam in 1948.

Photo 6 shows the downstream contact of the concrete dam and the left abutment. The staining visible at the bedrock contact is believed to have come from a crack in the dam facing and not from water flowing along the base of the dam. At the time of inspection no water was flowing along the contact.

c. Appurtenant Structures

Spillway

The spillway is an integral part of the main dam as shown in Photos 1, 2 and 3. The spillway section extends from the right abutment to a point about 40 feet right of the control structure, a distance of 186 feet along the dam crest. Spillway concrete appears in good condition with no evidence of cracking or spalling, and only minor erosion. Thirty inch high flashboards, in place at the time of inspection, are removed in the fall to prevent ice and debris damage. The flashboard supports are on 30 inch centers installed in openings intended for flashboard attachment.

SECTION 2: ENGINEERING DATA

2.1 DESIGN

a. Available Data - The available data consists of two plans "Village of Hardwick, Vermont, Repairs to Pottersville Dam", Charles T. Main, Inc., Boston, Massachusetts, November 15, 1945, Sheets 1341-11 and 1341-12.

b. Design Features - The drawings, computations and inspection reports indicate the design features stated in Section 1.

c. Design Data - Design data consists of information on the drawings by Charles T. Main, Inc. as listed in "Existing Plans".

2.2 CONSTRUCTION

a. Available Data - Information as contained in any plans, drawings, or specifications previously listed in "Design Data" or Appendix B.

b. Construction Considerations - Since the only available plans are for repairs rather than original design there was no practical means to ascertain any construction changes.

2.3 OPERATION

Pond level observations are made as needed, in order to coordinate the power generation with the available water supply. When ice conditions are not present, flashboards are used to increase the reservoir pool.

2.4 EVALUATION

a. Availability - Existing data was provided by the Village of Hardwick (the owner) who also made the operations available for visual inspection.

b. Adequacy - Detailed hydrologic/hydraulic data were not available. Design data and field measurements were utilized in conjunction with New England Division - Army Corps of Engineers "Preliminary Guidance for Estimating Maximum Probable Discharges" to perform the computations of outflow capacity.

The detailed engineering data required to perform an in-depth stability analysis of the dam was not available. The final assessment of the dam, therefore, must be based primarily on visual inspection, performance history, and spillway capacity computations.

c. Validity - A comparison of records, data, and visual observations reveals no significant discrepancies between available plans and as-built dimensions.

- | | | |
|----|---------------------------|--|
| 6. | Downstream channel: | moderately steep,
bedrock exposed |
| 7. | General: | N/A |
| j. | <u>Regulating Outlets</u> | |
| 1. | Invert: | 728.0 |
| 2. | Size: | 6 foot diameter |
| 3. | Description: | steel lined concrete
sluiceway |
| 4. | Control Mechanism: | manually operated gear
reducer |
| 5. | Other: | two 6 foot diameter
steel penstocks |

4.	Top of dam	615± acre-ft
5.	Test flood pool	1150± acre-ft
f.	<u>Reservoir Surface</u>	
1.	Normal pool	12± acres
2.	Flood control pool	N/A
3.	Spillway crest	12± acres
4.	Test flood pool	180± acres
5.	Top of dam	80± acres
g.	<u>Dam</u>	<u>Dike</u>
1.	Type: concrete gravity	concrete
2.	Length: 384 ft	125 ft
3.	Height: 51.87 ft	16 ft
4.	Top Width: 5 ft	3 ft
5.	Side Slopes: N/A	N/A
6.	Zoning: N/A	N/A
7.	Impervious Core: N/A	N/A
8.	Cutoff: N/A	N/A
9.	Grout curtain: N/A	N/A
10.	Other: N/A	N/A
h.	<u>Diversion and Regulating Tunnel</u>	N/A
i.	<u>Spillway</u>	
1.	Type:	ogee concrete
2.	Length of Weir:	186 feet
3.	Crest elevation w/o flashboards:	762.0
	w/flashboards:	764.5
4.	Gates:	N/A
5.	Upstream channel:	Wolcott Dam impoundment

7.	Total spillway capacity at test flood el. 781.5	60862 cfs
8.	Total project discharge at top of dam el. 770.87	20250± cfs
9.	Total project discharge at test flood el. 781.5	114800 cfs
c.	<u>Elevation (Feet NGVD)</u>	
1.	Streambed at toe of dam	719.0
2.	Bottom of cutoff	N/A
3.	Maximum tailwater	N/A
4.	Recreation pool	N/A
5.	Full flood control pool	N/A
6.	Spillway crest (ungated)	762.0 w/o flashboards 764.5 w/flashboards
7.	Design surcharge	N/A
8.	Top of dam	770.87
9.	Test flood surcharge	781.5
d.	<u>Reservoir</u>	
1.	Normal pool	2500± ft
2.	Flood control pool	N/A
3.	Spillway crest pool	2500± ft
4.	Top of dam	11000± ft
5.	Test flood pool	21000± ft
e.	<u>Storage</u>	
1.	Normal pool	258± acre-ft
2.	Flood control pool	N/A
3.	Spillway crest pool w/o flashboards w/flashboards	258± acre-ft 340± acre-ft

h. Design and Construction History - The following information is believed to be accurate based upon plans and correspondence available and from conversations with persons familiar with the history of the dam. Information pertaining to the original construction, believed to be about 1920, was not available. The powerhouse reportedly incurred extensive flood damage in 1927 and was repaired at that time. The power station was rebuilt and existing generation equipment installed in 1937. Repairs to the dam were designed in 1945 by Charles T. Main, Inc. and performed in 1948 by O. W. Miller for the Village of Hardwick.

i. Normal Operation Procedures - Flashboards are installed to a level of 2.5 feet above the spillway crest when ice conditions are unlikely. Pond level is regulated as necessary to coordinate power generation with available flow. At times of low flow, power generation is curtailed in the evening to restore the pond level. An operator is on duty when the station is operating.

1.3 PERTINENT DATA

a. Drainage Area - 134.7 square miles of moderately steep, relatively undeveloped terrain which is approximately 40% open and 60% wooded.

b. Discharge at Dam Site - Discharge is from over the spillway and through the 72 inch low level outlet and two 72 inch penstocks. Elevations are referenced to NGVD datum.

1. Outlet works

One 72" steel lined pipe @ invert el. 728.0	1400± cfs
--	-----------

Two 72" steel penstocks @ invert el. Unknown	Unknown
---	---------

2. Maximum known flood at dam site	N/A
------------------------------------	-----

3. Ungated spillway capacity at top of dam el. 770.87 (w/o flashboards)	18672 cfs
---	-----------

4. Ungated spillway capacity at test flood el. 781.5	60862 cfs
---	-----------

5. Gated spillway capacity at normal pool el. 762.0 (w/o flashboards)	N/A
---	-----

6. Gated spillway capacity at test flood el. 781.5	N/A
---	-----

The two spillway sections have crest elevations of approximately 762.0, a maximum of 43 feet in height above the streambed. Two and one-half feet of flashboard increase the spillway elevation to 764.5. The spillways have an ogee crest with a downstream slope of 7-5/8 horizontal to 12 vertical.

The central sluiceway pier, also with downstream slope of 7-5/8 horizontal to 12 vertical, has a breadth of 12 feet and a crest length of approximately 13.3 feet at elevation 772.0. A 6 foot diameter steel lined sluiceway, approximately 34 feet in length, runs through the pier at invert elevation 728.0. The manually operated gate control mechanism is accessed via a footbridge from the left abutment section.

The left abutment section, 174 feet in length, has a crest elevation of 770.87 and houses the intake structure consisting of two 6 foot diameter steel penstocks with trashracks and gates enclosed in a wooden gate house. A downstream training wall extends from the right end of this abutment.

Approximately 150 yards upstream of the dam site is a reinforced concrete dike on the right of the pool. The 16 foot high dike is approximately 125 feet long with a 3 foot broad crest at approximate elevation 770.2.

Elevations are referenced to NGVD datum.

No instrumentation exists at this dam site.

c. Size Classification - INTERMEDIATE - The dam impounds approximately 615 acre-feet of water with the pond level at the top of the dam, which at elevation 770.87 is 51.87 feet above the streambed elevation. Because the height is between 40 and 100 feet, the dam is classified as intermediate in size according to the Recommended Guidelines.

d. Hazard Classification - HIGH - If the dam were to be breached, there is potential for considerable property damage and loss of more than a few lives. Ten to fifteen houses in the Town of Wolcott would be flooded with depths up to 4.5 feet above sill elevation. Failure flows would also damage the power plant 175 yards downstream of the dam, the pair of highway bridges on Vermont Route 15, the Lamoille Valley Railroad bridge and the town road bridge in Wolcott.

e. Ownership - Village of Hardwick
Hardwick, Vermont 05843
(802) 472-5201

f. Operator - Mr. William Fee, Superintendent
Village of Hardwick Electrical Department
Church Street
Hardwick, Vermont 05843
(802) 472-5201

g. Purpose of Dam - The dam is used for power generation utilizing one vertical Smith-Kaplan turbine of 800 KW capacity, normally producing 600 KW at a 2400 V line voltage.

PHASE I INSPECTION REPORT

WOLCOTT DAM

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority - Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. James W. Sewall Company has been retained by the New England Division to inspect and report on selected dams in the State of Vermont. Authorization and notice to proceed were issued to James W. Sewall Company under a letter of April 2, 1980 from William E. Hodgson, Jr. Colonel, Corps of Engineers. Contract No. DACW 33-80-C-0051 has been assigned by the Corps of Engineers for this work.


b. Purpose of Inspection Program - The purposes of the program are to:

1. Perform technical inspection and evaluation of non-federal dams to identify conditions requiring correction in a timely manner by non-federal interests.
2. Encourage and prepare the States to quickly initiate effective dam inspection programs for non-federal dams.
3. To update, verify and complete the National Inventory of Dams.

1.2 DESCRIPTION OF PROJECT

a. Location - The dam is located on the Lamoille River in the Village of Pottersville, Town of Wolcott, County of Lamoille, State of Vermont. The dam is shown on the Hardwick USGS Quadrangle Map (15' series) having coordinates latitude N 44° 32.2' and longitude W 72° 26.7'. The dam is popularly called Pottersville Dam.


b. Description of Dam and Appurtenances - The dam, originally constructed about 1920 and refaced in 1948, is a reinforced concrete gravity structure 51.87 feet high, built on ledge rock and having a total length of approximately 384 feet. This includes a 120 foot long spillway section on the right side of the dam, a central sluiceway pier with outlet works, a 66 foot long spillway section to the left of the sluiceway pier, and an abutment section with intake structure for power generation on the left side of the dam.



WOLCOTT DAM

USGS QUADRANGLES
HARDWICK, VT. 1951
PLAINFIELD, VT. 1953

LOCATION MAP
VERMONT





U.S. ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY
CONSULTANTS
OLD TOWN, MAINE

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Wolcott Dam - VT 00179

Wolcott, Vermont

April 22, 1980

<u>Section</u>	<u>Page</u>
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-1
6. EVALUATION OF STRUCTURAL STABILITY	6-1
6.1 Visual Observation	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Changes	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	7-1
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
7.4 Alternatives	7-2

APPENDIX

APPENDIX A - VISUAL CHECK LIST WITH COMMENTS	A-1
APPENDIX B - ENGINEERING DATA	B-1
APPENDIX C - DETAIL PHOTOGRAPHS	C-1
APPENDIX D - HYDRAULICS/HYDROLOGIC COMPUTATIONS	D-1
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	E-1

SECTION 5: EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 GENERAL

The project is basically a run-of-the-river dam used for power generation, with impoundment surface area changing dramatically with water level.

The tributary watershed consists of 134.7 square miles of moderately steep terrain which is approximately 60% wooded and 40% open. Contained within this drainage area are several small lakes, including Hardwick Lake, Caspian Lake, Eligo Pond, Nichols Pond, Long Pond, East Long Pond and Flagg Pond. The total surface area of these lakes is less than 2% of the entire watershed area, thus their storage effect on the peak inflow to the Wolcott Dam impoundment was deemed negligible.

Wolcott Dam is a concrete gravity structure equipped 186 feet of ogee crest spillway. The spillway will pass approximately 16% of the project Test Flood with the dam overtopped by 10.6 feet.

5.2 DESIGN DATA

No design data are known to exist for the project.

5.3 EXPERIENCE DATA

A flood in 1927 reportedly caused extensive damage to the power house. No other information on serious problem situations arising at the dam was found and it does not appear the dam has been overtopped.

5.4 TEST FLOOD ANALYSIS

The Test Flood for this high hazard, intermediate size dam is equivalent to the Probable Maximum Flood (PMF). Based upon the "Rolling" guide curve from the "Preliminary Guidance for Estimating Maximum Probable Discharge", dated March, 1978, peak inflow to Wolcott Dam flowage is 117,863 cfs. Assuming the reservoir to be initially at spillway crest elevation (762 NGVD) routed Test Flood outflow is 114,800 cfs with the dam overtopped by 10.6 feet. Based upon our hydraulics computations, the spillway capacity is approximately 16% of the routed Test Flood outflow at the top of the dam.

5.5 DAM FAILURE ANALYSIS

The impact of dam failure was assessed utilizing the April, 1978, "Rule of Thumb Guidance for Estimating Downstream Dam Failure Hydrographs".

With the reservoir water surface elevation initially at the top of the dam (el. 770.87 NGVD), the peak failure outflow would be 44,200 cfs causing a rise in stage in the Town of Pottersville of 3.5 feet and a rise in stage in the Town of Wolcott of 3.3 feet. It appears that the pre-failure flow would cause the most significant damage with a maximum depth of 9 feet at the houses in Wolcott.

The preceding analysis indicated little additional stage or hazard due to dam failure under full spillway pre-failure conditions. As the failure flow was significant an analysis with the reservoir water surface elevation initially at the spillway crest (el. 762 NGVD) was undertaken to establish the "low flow" failure hazard. The peak failure outflow under this condition would be 22,800 cfs. The pre-failure flow would remain within the bounds of the stream bed while the routed failure flood would inundate a large area outside of the stream bed up to a depth of 4.5 feet. The rapid rise in flood stage would severely damage the power plant 175 yards downstream of the dam, destroy the pair of Route 15 highway bridges, the Lamoille Valley Railroad crossing, and the town road crossing in Wolcott. The Town of Wolcott is located on a relatively level flood plain and the failure flood could damage 10-15 homes with a maximum water level of 4.5 above sill elevation. There is potential for the loss of more than a few lives in the Town of Wolcott. Based on this analysis, Wolcott Dam has been classified as a "High Hazard" dam.

SECTION 6: EVALUATION OF STRUCTURAL STABILITY

6.1 VISUAL OBSERVATION

The visual inspection did not disclose any immediate stability problems. Seepage and spalling noted at the dam and the dike are judged to be minor in nature.

6.2 DESIGN AND CONSTRUCTION DATA

No original design and construction data are available for the dam. However, there are drawings for repairs which show plans and sections of the dam and indicate that the dam rests on bedrock.

6.3 POST-CONSTRUCTION CHANGES

Drawings indicate that a concrete facing was placed on the upstream and downstream face of the dam. Records indicate this work was performed in 1948. The concrete facing is 12 inches thick on the downstream face of the spillway and 8 inches thick on the upstream face of the dam and downstream face of the sluiceway pier. This concrete facing is tied to the existing concrete with steel dowels 3 feet on center in both directions. A construction joint drainage system consisting of 6 inch diameter tile drains was installed between the new facing and the existing dam. Openings for flashboard attachment were installed at the spillway crest. It is not known what provision, if any, was made in the original design for the additional hydrostatic head which flashboards impose.

6.4 SEISMIC STABILITY

The dam is located in Seismic Zone 2 and in accordance with the recommended Phase I guidelines, does not warrant seismic investigation.

SECTION 7: ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Condition - Based upon the visual inspection, the dam is judged to be in fair condition. This assessment is predicated primarily upon concerns regarding spillway hydraulic capacity and effect of flashboards on dam stability. Structural and mechanical condition is good.

b. Adequacy of Information - Due to the lack of design and construction data for this dam, the assessment of safety is based solely on the visual inspection.

c. Urgency - The recommendations and remedial measures presented below should be implemented by the owner within one year after receipt of this Phase I Inspection Report.

7.2 RECOMMENDATIONS

The owner should engage a qualified registered engineer to undertake further investigations as follow:

- a. Assess significance of the seepage occurring on the downstream faces of the dam and the dike and design remedial measures if needed.
- b. Determine the effect of the currently-used flashboard system on dam stability.
- c. Perform a detailed hydraulic and hydrologic study to further assess the need for and the means to increase the project discharge capacity.
- d. The moss, trees, and debris on the face and within 10 feet of the toe of the dike should be removed by the owner.

The owner should implement all recommendations by the engineer.

7.3 REMEDIAL MEASURES

- a. The eroded concrete on the sluice gate control enclosure should be repaired by the owner.
- b. The crack at the bend in the left abutment wall should be repaired by the owner.
- c. The spalled concrete on the face of the dike should be removed and the areas patched by the owner.
- d. Areas of seepage at the base of the dam and the dike should be monitored monthly by the owner, and technical assistance sought upon any major quantity increase.

- e. A program of biennial technical inspection, with repairs as necessary should be instituted by the owner.
- f. A formal downstream warning system to be implemented in the event of flood flow or imminent dam failure conditions should be developed by the owner.

7.4 ALTERNATIVES

This study has identified no practical alternative to the above recommendations.

APPENDIX A
VISUAL CHECK LIST WITH COMMENTS

**VISUAL INSPECTION CHECKLIST
PARTY ORGANIZATION**

PROJECT Wolcott Dam

DATE May 6, 7, 8, 1980

TIME 3:00 10:00

WEATHER Cloudy, mild

W.S. ELEV. _____ U.S. _____ DN.S. _____

PARTY:

- | | | |
|------------------------------|------------|-----------|
| 1. <u>Stephen D. Murray</u> | <u>SDM</u> | 6. _____ |
| 2. <u>Rodney L. Hanscom</u> | <u>RLH</u> | 7. _____ |
| 3. <u>Charles A. Heney</u> | <u>CAH</u> | 8. _____ |
| 4. <u>Daniel P. La Gatta</u> | <u>DPL</u> | 9. _____ |
| 5. <u>Peter Barranco</u> | | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Concrete Dam</u>	<u>SDM, RLH, CAH, DPL</u>	
2. <u>Concrete Dike</u>	<u>SDM, RLH, CAH</u>	
3. <u>Gate House</u>	<u>SDM, RLH, CAH</u>	
4. <u>Sluice Gate and Conduit</u>	<u>SDM, RLH, CAH</u>	
5. <u>Outlet Channel</u>	<u>SDM, RLH, CAH, DPL</u>	
6. <u>Spillway Weir and Discharge Channel</u>	<u>SDM, RLH, CAH, DPL</u>	
7. <u>Service Bridge</u>	<u>SDM, RLH, CAH</u>	
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

PROJECT Wolcott DamDATE May 6, 7, 8, 1980PROJECT FEATURE Concrete DamNAME SDM, RLH,DISCIPLINE James W. Seval Co.
Geotechnical Engineers Inc.NAME CAH, DPL

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	Concrete dam founded on bedrock. Bedrock is exposed along entire length of dam.
Crest Elevation 770.87	
Current Pool Elevation ^{May 6} 761	
^{May 7} 765	
Maximum Impoundment to Date	
Surface Cracks	Vertical crack at bend of abutment
Pavement Condition	Good
Movement or Settlement of Crest	None observed
Lateral Movement	None observed
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Conditions at abutment contact are good. Slight leakage at interface at outcrop along left abutment and at toe.
Indications of Movement of Structural Items on Slopes	
Trespassing on Slopes	None
Sloughing or Erosion of Slopes or Abutments	None
Rock Slope Protection - Riprap Failures	No riprap
Unusual Movement or Cracking at or Near Toe	None observed
Unusual Embankment or Downstream Seepage	N.A.
Piping or Boils	N.A.
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None
Vegetation	N.A.

PROJECT Wolcott Dam DATE May 6, 7, 8, 1980
 PROJECT FEATURE Concrete dike NAME SDM, ALH
 DISCIPLINE James W. Sewall Co. NAME CAH, DPL
Geotechnical Engineers Inc.

AREA EVALUATED	CONDITION
DIKE EMBANKMENT	Concrete dike 150 yards above dam, right side
Crest Elevation	770
Current Pool Elevation	May 8 765
Maximum Impoundment to Date	
Surface Cracks	Minor
Pavement Condition	Minor efflorescence, considerable spalling
Movement or Settlement of Crest	No
Lateral Movement	No
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Good
Indications of Movement of Structural Items on Slopes	No
Trespassing on Slopes	No
Sloughing or Erosion of Slopes or Abutments	No
Rock Slope Protection - Riprap Failures	N.A.
Unusual Movement or Cracking at or Near Toes	No
Unusual Embankment or Downstream Seepage	Very minor seepage at base of wall, downstream end
Piping or Boils	Slight seepage from 2" plugged pipe in wall
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None
Vegetation	Moss and several small trees growing on dike

PROJECT Wolcott Dam

DATE May 6, 7, 8, 1980

PROJECT FEATURE _____

NAME SDM, RLH

DISCIPLINE James W. Sewall Co.
Geotechnical Engineers Inc.

NAME CAH, DPL

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <p> Slope Conditions</p> <p> Bottom Conditions</p> <p> Rock Slides or Falls</p> <p> Log Boom</p> <p> Debris</p> <p> Condition of Concrete Lining</p> <p> Drains or Weep Holes</p> <p>b. Intake Structure</p> <p> Condition of Concrete</p> <p> Stop Logs and Slots</p>	<p><i>No approach channel</i> <i>Penstocks built into dam</i></p>

PROJECT Wolcott Dam
PROJECT FEATURE Gate House
DISCIPLINE James W. Sewall Co.
Geotechnical Engineers Inc.

DATE May 6, 7, 8, 1980
NAME SDM, RLH
NAME CAH, DPL

AREA EVALUATED	CONDITION
OUTLET WORKS - CONTROL TOWER <i>Gate House</i>	
a. Concrete and Structural	
General Condition	<i>Good</i>
Condition of Joints	<i>Good</i>
Spalling	<i>Minor spalling downstream face</i>
Visible Reinforcing	<i>None</i>
Rusting or Staining of Concrete	<i>Minor</i>
Any Seepage or Efflorescence	<i>Minor efflorescence</i>
Joint Alignment	<i>Good</i>
Unusual Seepage or Leaks in Gate Chamber	<i>No</i>
Cracks	<i>None observed</i>
Rusting or Corrosion of Steel	<i>Minor rusting</i>
b. Mechanical and Electrical	
Air Vents	<i>N. A.</i>
Float Wells	<i>N. A.</i>
Crane Hoist	<i>For trans. rake rake, good condition</i>
Elevator	<i>N. A.</i>
Hydraulic System	<i>N. A.</i>
Service Gates	<i>For penstock gates, good condition</i>
Emergency Gates	<i>N. A.</i>
Lightning Protection System	<i>N. A.</i>
Emergency Power System	<i>N. A.</i>
Wiring and Lighting System	<i>Fair condition</i>

PROJECT Wolcott Dam DATE May 6, 7, 8, 1980
PROJECT FEATURE Sluice Gate and Conduit NAME S.D.M., R.L.H.
DISCIPLINE James W. Sennell Co. NAME CAH, DPL
Geotechnical Engineers Inc.

AREA EVALUATED	CONDITION
OUTLET WORKS - TRANSITION AND CONDUIT	
General Condition of Concrete	Good
Rust or Staining on Concrete	Rust stains below conduit outlet
Spalling	None
Erosion or Cavitation	Moderate erosion of sluice control enclosure at water line
Cracking	
Alignment of Monoliths	N.A.
Alignment of Joints	No misalignment
Numbering of Monoliths	N.A.

PROJECT Wooten Dam DATE May 6, 1980
 PROJECT FEATURE Outlet Channel NAME SDM, ALH
 DISCIPLINE James W. Sevall Co. NAME CAH, DPL
Geotechnical Engineers Inc.

AREA EVALUATED	CONDITION
OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL	Penstocks are main outlet. Low-level outlet is a conduit through base of dam.
General Condition of Concrete	
Rust or Staining	N.A.
Spalling	N.A.
Erosion or Cavitation	N.A.
Visible Reinforcing	N.A.
Any Seepage or Efflorescence	N.A.
Condition at Joints	N.A.
Drain holes	N.A.
Channel	
Loose Rock or Trees Overhanging Channel	None
Condition of Discharge Channel	Good

PERIODIC INSPECTION CHECKLIST

PROJECT Wolcott Dam DATE May 6, 7, 8, 1980
 PROJECT FEATURE Spillway Weir and Discharge Channel NAME SDM, RLH
 DISCIPLINE James W. Sewall Co. NAME CAH, DPL
Geotechnical Engineers Inc.

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u>	
Approach Channel	No approach channel. Spillway is integral with dam
General Condition	
Loose Rock Overhanging Channel	
Trees Overhanging Channel	
Floor of Approach Channel	
Weir and Training Walls	
General Condition of Concrete	Good
Rust or Staining	Small rust stain to right of conduit outlet
Spalling	No
Any Visible Reinforcing	No
Any Seepage or Efflorescence	Minor efflorescence
Drain Holes	None visible
Discharge Channel	
General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Channel	Bedrock - clear
Other Obstructions	None

⑨ AND ⑩ TAKEN AT DIKE AT REAR OF IMPOUNDMENT




PHOTO LOCATION PLAN
WOLCOTT DAM

⑬ TAKEN DOWNSTREAM
→

SCALE



APPENDIX C
DETAIL PHOTOGRAPHS

3-11-80

APB

WOLCOTT DAY

VT7420 16-129

$$\begin{array}{r} sh=hh = 773 \\ -719 \\ \hline 54' \end{array}$$

class < possible

$$L = 8 + 120 + 13 + 66 + 120 + 12 + 15 = 384'$$

$$Spillway = 120 + 66 = 186'$$

$$Q = (3.0)(100)(9)^{1/5} = 19,084 \quad (19,000)$$

$$SA = 200 \times 250 = 50,000 \quad \text{300 Remd length of power}$$

$$\text{Vol. @ NWL} = 12 \times 46 \times .4 = 221 \text{ AF} \quad (200)$$

$$SAH \quad SA = 6A \quad \text{Vol} = 3 \times 10^6 / 15500 = 69 \text{ AF}$$

$$\text{AP road} = .3 \text{ mi}^2 \quad \frac{(3(5200)(600))}{13,560} = 7 \text{ AF}$$

$$\frac{1}{6} \text{ FB} \quad 7 \times 48 = 134 \text{ AF}$$

INSPECTION REPORT
ON

Wolcott Dam

1. Date of inspection May 9, 1953 2. Water conditions Spilling over
Part of crest

GENERAL DATA:

3. Location of dam Lamoille River, town of Wolcott.
4. Owner and operator Village of Hardwick
5. Characteristic features of dam Concrete gravity dam about 50
ft. high, rebuilt in 1948.
6. Other related data Contained in writer's initial report
on structure.

OBSERVATIONS:

7. Condition of structure No appreciable change

8. Condition of equipment Satisfactory

9. Operation Satisfactory

10. Maintenance Satisfactory

REMARKS:

Dam remains in a good condition.

Inspected by Stephen H. Hight

Conclusions:

From the inspection made of Wolcott Dam, the writer concludes that the structure, as repaired last year, is in a sound condition. It can safely accommodate floods equal in size to any previous recorded flood.

Stephen H. Haybrook
STEPHEN H. HAYBROOK
FEDERAL ENGINEER

Public Service Commission
Montpelier, Vermont
September 8, 1942

REPORT NO. 71

corresponding base width of about 40 feet. The spillway is shaped with conventional curved crest and discharge face. Flashboards are built up to a level 2.5 feet above the spillway crest.

An intake is located in the abutment section and adjacent to the spillway. Trashracks and gates are enclosed in a wooden building. From here the flow is diverted through two 6-foot diameter steel penstock to the power house further downstream.

A 6-foot diameter sluiceway is also provided in a pier through the spillway section at its maximum depth. Access to the sluiceway is provided by a footbridge from the left abutment section.

Details of the dam are indicated in the attached drawings.


Condition of the Dam:

This dam was examined by the writer on June 15, 1949 and appeared in excellent condition. As indicated by the photograph, the dam has undergone a refacing operation, which was completed in November, 1948. The work was done under the supervision of the Chas. T. Main, Inc. engineering firm in accordance with the drawings attached hereto.

The repairs accomplished last year consisted of the chipping off of the old, deteriorated concrete on exposed surfaces and the replacing it with a ~~thickness~~ ^{thickness} of at least 8 inches of new concrete bonded to the old concrete core with reinforcement mesh and dowels. The method used is an accepted procedure in such repair jobs and, from appearances, the work was soundly executed.

Some leakage was observed at the base of the intake structure. Indications were that this leakage originates elsewhere along the abutment section, probably at the joint between the dam and the foundation. However, the quantity of leakage is not sufficient to cause any concern.

REPORT ON WOLCOTT DAM



Wolcott Dam (Spillway Section)

Wolcott Dam is one of the developments on the Lamoille River belonging to the Village of Hardwick. It is located in the Village of Pottersville in the Town of Wolcott, Vermont and is sometimes called Pottersville Dam. It serves as a diversion structure for a hydroelectric power plant.

The drainage area to the dam is about 130 square miles. At full pond level, the reservoir has a surface area of about 6 acres and impounds about 3,000,000 cubic feet of water.

Description:

Wolcott Dam is a solid, gravity-type, concrete structure on ledge rock. It has a total length of about 390 feet, including a spillway section in the main river channel at the north half of the dam. The net spillway length is 126 feet with the crest 9 feet below the top of the dam. In cross-section, the spillway has a maximum depth of 50 feet and

STATE OF VERMONT
PUBLIC SERVICE COMMISSION

Electric-Utility Dams

DEC 1 8 17 AM 1947

1. Name of Dam: Wolcott
2. Owner of Dam: Village of Hardwick
3. Located in What Town: Wolcott
4. Is the Dam in Use: yes
5. Name of Lake, Pond, River, Brook, Creek, Etc., on Which Located:
Lamoille River
6. Material Used in Construction of the Dam:
Concrete
7. Purpose for Which Dam is Used:
Power generation
8. Is Dam Attended or Unattended:
Yes
9. Approximate Surface Area of the Body of Water Impounded by Dam:
acre
10. Approximate Volume of Water, in Cubic Feet, Impounded by Dam when in Full Use:
3,268,000 gals
11. Regulations Governing the Operation of the Dam:
none
12. Remarks:

This dam is to be reconditioned next year. Survey work was completed in 1945, but have been unable to give up use of same until there is more power available from other sources.

Utility: Village of Hardwick

Signed:

Ray W. Lamoille
(Title)

SUMMARY OF DATA AND CORRESPONDENCE

<u>DATE</u>	<u>TO</u>	<u>FROM</u>	<u>SUBJECT</u>	<u>PAGE</u>
10/1/47	St. of Vt. Public Ser. Comm.	G.W. Larrabee, Treas. Village of Hardwick	Information Sheet	B-4
9/8/49	File	Stephen H. Haybrook Hydraulic Engineer Public Ser. Comm.	Detailed Dam Inspec. Report (1 year after dam refacing)	B-5
5/9/53	File	Stephen H. Haybrook Hydraulic Engineer Public Ser. Comm.	Dam Inspection Report	B-8
3/11/80	File	A. P. Barranco Dam Safety Engineer Vt. Dept. of Water Resources	Storage and Spillway Capacity Calculations	B-9




WOLCOTT DAM

EXISTING PLANS

On file with the Village of Hardwick:

"Village of Hardwick, Vermont
Repairs to Pottersville Dam
Charles T. Main, Inc., Architects - Engineers
Boston, Massachusetts
November 15, 1945
5 Sheets - Blueprints

REPRODUCED AT GOVERNMENT EXPENSE






NOTE:
THIS PLAN COMPILED FROM EXISTING
PLANS FOR THE DAM RECONSTRUCTION
IN 1946, BY CHAS. T. MAIN, INC.,
ENGINEERS, AND MODIFIED AS OBSERVED
IN THE FIELD.

1A
SHEET 16

<p>ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASSACHUSETTS</p>	<p>JAMES W. SEWELL COMPANY CONSULTING ENGINEERS 20 South Street Boston, Mass. 02108 Tel. 5-1111</p>	<p>NATIONAL PROGRAM OF INSPECTION OF NON-FEDERAL DAMS</p> <p>WOLCOTT DAM WOLCOTT, VT.</p>
---	---	--

LAMOILLE RIVER




SECTION BB




ELEV 762.00

ELEV 719.00 ±




SECTION AA



APPENDIX B
ENGINEERING DATA

PROJECT Wolcott Dam DATE May 6, 7, 8, 1980
 PROJECT FEATURE Service Bridge NAME SDM, RLH,
 DISCIPLINE James W. Sewall Co. NAME CAH, DPL
Geotechnical Engineers Inc.

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - SERVICE BRIDGE</u>	
a. Super Structure	Service Bridge goes from abutment to sluiceway pier
Bearings	Moderate amount of rusting
Anchor Bolts	Good
Bridge Seat	Good
Longitudinal Members	Good
Underside of Deck	Good
Secondary Bracing	Good
Deck	Good
Drainage System	N.A.
Railings	Good
Expansion Joints	N.A.
Paint	Fair
b. Abutment & Piers	
General Condition of Concrete	Good
Alignment of Abutment	Good
Approach to Bridge	Good
Condition of Seat & Backwall	Good



(1), (2), and (3) Panorama of Downstream Face

C-2

U.S. ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS
JAMES W. SEWALL COMPANY
CONSULTANTS
OLD TOWN, MAINE

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Wolcott Dam - VT 00179
Wolcott, Vermont
May 6, 1980



(4) Penstocks, Powerhouse Downstream of Dam - May 6, 1980



(5) Right Abutment Bedrock
May 6, 1980

U.S. ARMY ENGINEER DIV, NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY
CONSULTANTS
OLD TOWN, MAINE

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Wolcott Dam
Wolcott, Vermont
VT 00179
May, 1980

C-3



(6) Left Abutment Bedrock
May 6, 1980



(7) Left Abutment, Upstream Face, and Gatehouse - May 6, 1980


U.S. ARMY ENGINEER DIV, NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY
CONSULTANTS
OLD TOWN, MAINE


NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Wolcott Dam
Wolcott, Vermont
VT 00179
May, 1980

C-4



(8) Reservoir Outlet Gate Controls
May 6, 1980



(9) Concrete Dike Upstream of Dam
May 8, 1980

U.S. ARMY ENGINEER DIV, NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY
CONSULTANTS
OLD TOWN, MAINE


NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Wolcott Dam
Wolcott, Vermont
VT 00179
May, 1980

C-5



(10) Face of Concrete Dike (Metal
Scrap in Foreground)
May 8, 1980



(11) Downstream Channel, Powerhouse in Left Background - May 6, 1980

U.S. ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

JAMES W. SEWALL COMPANY
CONSULTANTS
OLD TOWN, MAINE

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Wolcott Dam
Wolcott, Vermont
VT 00179
May, 1980

C-6



(12) Downstream Channel and Face of Dam After Heavy Showers
May 7, 1980



(13) Vermont Route 15 Bridges Downstream of Dam - May 8, 1980

U.S. ARMY ENGINEER DIV, NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS


JAMES W. SEWALL COMPANY
CONSULTANTS
OLD TOWN, MAINE

NATIONAL PROGRAM OF
INSPECTION OF
NON-FED. DAMS

Wolcott Dam
Wolcott, Vermont
VT 00179
May, 1980

C-7

APPENDIX D
HYDRAULICS/HYDROLOGIC COMPUTATIONS




WOLCOTT DAM

DRAINAGE AREA
134.7 SQ. MILES

USGS QUADRANGLE
LAKE CHAMPLAIN N.Y. 1962
SCALE 1:250,000

L.R. JONES



Subject Inspection of non-federal dams

Computation Wolcott Dam

Job No. 953-05G

Computed by MEB

Checked by SDM

Date 8-12-80

Hydrologic / Hydraulic Inspection

I. Performance at Test Flood Conditions

A. Maximum Predicted Flood

a) Watershed classified as "rolling"

B) Watershed area

134.7 ac. Planimeter from USGS sheets
DMS, one of three trials

142 ac. V.L. Dept. of Water Resources Info Sheet

Source south of lake located within

the 100 ft. area, actually Houghton

Lake, Carleton Lake, Eagle Pond, East Long

and West Pond and Deer Pond.

Mean total surface area of lake is less than

25% for entire watershed area and thus

the direct effect of these lakes is

decreased significantly.

C) From MED-ACE "Preliminary Guidance for
Estimating Max. Possible Discharges" -
Graph Curve for F1/F - Peak Flow Rates

Plot E: 3.75 cfs/acre^2 for Total Discharge Area

$F1/F \rightarrow 915 \text{ cfs/acre}^2 \times 134.7 \text{ ac}^2 = 123,176.5 \text{ cfs}$

$1/2 F1/F = 59,931 \text{ cfs}$

Subject Inspection of non-fed dams

Computation Wolcott Dam

Job No. 953-050

Computed by NER

Checked by SDM


Date 8-12-80

a) Test Flood

a) Classification of dams according to NED-ACE Recommended Guidelines

1. Size

Elevation vs. Surface Area



Elevation of Spillway = 772' Area of Watershed = 12.0 acres

Normal pool el. 762' 12 acres $\times .5' \times (762 - 741) = 126$ acre-ft

Top of dam el. 770.87' 12 acres $\times (770.87 - 762) = 107$ acre-ft

(6.8 acres $\times (770.87 - 762) \times .5' = 615$ acre-ft

See Stage-Storage Curve on p. 3

Storage (max) = 615 acre-feet (top of dam el. 770.87)
Height = $770.87' - 749' = 51.87'$

Project Inspection of non-federal dams


Location Wolcott Dam

Job No. 953-05G

Designed by meB

Checked by SDM

Date 8-12-80



Project Inspection of non-federal dams

Location Wolcott Dam Wolcott, VT Job No. 953-056

Designed by MEB Checked by SMY Date 8-13-80

2. Hazard Potential

Failure of this dam would cause the potential for
75 cubic feet of water to be released from the
of the dam. This would be a significant hazard to
the downstream community. The dam is a concrete
gravity dam with a spillway on the right side.
The dam is in good condition and no major
repairs are needed at this time.

3. Classification

Class 3 - Intermediate Hazard

HAZARD DAM

1. Total Volume of PHE = 117,863 cfs
2. PHE = 50,000 cfs

t Inspection of non-federal dams

ation Walcott Dam Walcott, Vt

Job No. 953-05-G

ed by MEB

Checked by SDM

Date 6-23-80

a) Surge at Peak Inflow

a) Peak Inflow $Q_p = 117863$ cfs
 $Q_p' = 58931$ cfs

b) Outflow Rating Curve

Highways 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

Water Pipe 10" x 10"

Water Pipe 10" x 10"

1	794	2	794
2	794	6	794
3	794	10	794
4	794	14	794
5	794	18	794
6	794	22	794
7	794	26	794
8	794	30	794
9	794	34	794
10	794	38	794
11	794	42	794
12	794	46	794
13	794	50	794
14	794	54	794
15	794	58	794
16	794	62	794
17	794	66	794
18	794	70	794
19	794	74	794
20	794	78	794
21	794	82	794
22	794	86	794
23	794	90	794
24	794	94	794
25	794	98	794
26	794	102	794
27	794	106	794
28	794	110	794
29	794	114	794
30	794	118	794
31	794	122	794
32	794	126	794
33	794	130	794
34	794	134	794
35	794	138	794
36	794	142	794
37	794	146	794
38	794	150	794
39	794	154	794
40	794	158	794
41	794	162	794
42	794	166	794
43	794	170	794
44	794	174	794
45	794	178	794
46	794	182	794
47	794	186	794
48	794	190	794
49	794	194	794
50	794	198	794
51	794	202	794
52	794	206	794
53	794	210	794
54	794	214	794
55	794	218	794
56	794	222	794
57	794	226	794
58	794	230	794
59	794	234	794
60	794	238	794
61	794	242	794
62	794	246	794
63	794	250	794
64	794	254	794
65	794	258	794
66	794	262	794
67	794	266	794
68	794	270	794
69	794	274	794
70	794	278	794
71	794	282	794
72	794	286	794
73	794	290	794
74	794	294	794
75	794	298	794
76	794	302	794
77	794	306	794
78	794	310	794
79	794	314	794
80	794	318	794
81	794	322	794
82	794	326	794
83	794	330	794
84	794	334	794
85	794	338	794
86	794	342	794
87	794	346	794
88	794	350	794
89	794	354	794
90	794	358	794
91	794	362	794
92	794	366	794
93	794	370	794
94	794	374	794
95	794	378	794
96	794	382	794
97	794	386	794
98	794	390	794
99	794	394	794
100	794	398	794

Shedding Pen $L = 13-30$
 $C = 2.0$
Crest H.P. $EL. 772$

1	94	774
2	277	774
3	509	774
4	794	794
5	1096	794

Inspection of confederal dams

tion Waldcott Dam Waldcott Vt Job No. 95.3-050

d by D.E.R. Checked by SDM Date 8-12-80

Summary

a) Peak Failure Outflow

$Q_p = 44,200$ cfs (in form sheet = 20,250 cfs)

b) Approximate stage before failure

Impact Area: Potteryville $H = 13.3'$

Waldcott $H = 17.7'$

c) Approximate stage after failure

Impact Area: Potteryville $H = 16.8'$

Waldcott $H = 21.0'$

d) Rise in stage

Impact Area: Potteryville $\Delta H = 3.5'$

Waldcott $\Delta H = 3.3'$

The preceding dam failure analysis taken
at the crest of the dam, indicated
the dam stage of hazard was "Major Failure".
The following dam failure analysis will be
conducted at the spillway crest to establish
the "Major Failure" hazard.

Probable Flow = 1071 cfs

Reservoir Stage at Time of Failure = 258 acft-ft

Peak Failure Flow = Probable Outflow

(No probable spillway section
could be determined in previous
dam failure)

at Inspection of non-federal dams

ation Walcott Dam Walcott VT

Job No. 953-056


ed by mEB

Checked by SDM

Date 6-26-80

Downstream Channel @ Town of Walcott

Recur. #2



Project Inspection of non-federal dams

Station Walcott Dam Walcott, Vt

Job No. 953-056

Designed by MEB

Checked by SDM

Date 6-26-80

Downstream Channel @ Town of Walcott							Reach #2
Section 1 Flood Plain							
H	A	P	R	V	G		
10	30	66	0.5	.32	5		
12	2245	95	2.93	.93	211		
14	1225	179	4.21	1.34	581		
16	3225	405	5.88	1.65	1444		
18	6225	911	7.48	1.97	3651		
20	11225	202	10	2.28	8378		
22	18225	457	10.97	2.41	2213		
24	27225	1017	11.84	2.42	4178		
26	38225	181	12.26	2.58	5257		
28	50225	400	14.4	2.65	1456		
Section 2 Flood Plain							
H	A	P	R	V	G		
10	30	60	0.5	.32	5		
12	245	120	2	.82	196		
14	540	180	3	1.07	578		
16	950	240	4	1.20	1015		
18	1520	300	5	1.5	3257		
20	2160	360	6	1.74	8670		
22	2940	420	7	1.87	1826		
24	3840	480	8	2.00	2954		
26	4860	540	9	2.23	4081		
28	6000	600	10	2.24	14381		
Rating Curve (Continued)							
H	G	H	G				
10	5765	10	27083				
12	8572	12	33513				
14	12084	14	41222				
16	16311	16	49675				
18	21293	18	57514				

Project Inspection of non-federal dams

Location Walcott Dam Walcott, Vt

Job No. 953-056


Designed by MEB

Checked by SDH

Date 6-26-80

Downstream Channel @ Tail of Walcott Reach #2.

Approximate Cross-section



$$N = 1.486 R^{2/3} S^{1/2}$$

" "

$$S = .0017 \text{ (USGS sheet)}$$

$$n = 0.040 \text{ stream bed}$$

$$n = 0.16 \text{ floor plan}$$

$$Q = AV$$

H	A	P	F	V	Q
2	172	93	1.68	1.94	334
4	328	100	2.00	2.87	941
6	524	115	2.81	3.76	1970
8	728	131	3.57	4.47	3272
10	967	138	4.24	5.21	5053
12	1240	141	4.80	5.89	7287
14	1547	144	5.25	6.41	9945
16	1886	146	5.62	6.84	12846
18	2247	148	5.94	7.22	16285
20	2628	151	6.14	7.51	20097
22	3028	153	6.31	7.75	24253
24	3447	155	6.46	7.95	28852
26	3884	157	6.59	8.11	33897
28	4338	158	6.70	8.24	39482

ject Inspection of non-federal dams

putation Wolcott Dam

Job No. 953-056

puted by MEB

Checked by SDM

Date 8-8-80

Reach #2

3000 - 5500 ft. D/S of the dam

Road crossing at D/S end of reach @ Town of Wolcott

Pre-failure Stage $Q_s = 20250$ cfs $H = 17.7'$
(Stage - Discharge curve plotted on p. 18)

Volume between pre-failure and post-failure stages:

$$Q_{p1} = 37400 \text{ cfs } H = 23.1'$$

$$V_1 = 438 - 246 = 192 \text{ acre-ft (x-sect following page)}$$

$$V_1 < 1/2 S \therefore O.K.$$

$$Q_{p2} (\text{Trial}) = Q_{p1} (1 - \frac{V_1}{S})$$

$$= 37400 (1 - \frac{192}{615})$$

$$\approx 25700 \text{ cfs}$$

$$H = 19.6'$$

$$V = 307 - 246 = 61 \text{ acre-ft}$$

$$Q_{p2} = Q_{p1} (1 - \frac{V_{ov}}{S})$$

$$= 37400 (1 - \frac{(192+61)/2}{615})$$

$$\approx 29700 \text{ cfs}$$

Post-failure Stage $Q_p = 29700$ cfs $H = 21'$

$$\text{Raise in stage} = 21 - 17.7 = 3.3'$$

Subject Inspection of non-federal dam


Computation Wolcott Dam Wolcott Vt

Job No. 953-056

Computed by MEB

Checked by SDM

Date 2-26-80




Computation Wolcott Day Wolcott VT Job No. 953-056

Computed by MP Checked by SDM Date 6-26-80

D/S Channel at Route 15 crossing Reach #11

Approximate Cross-section



Mapping $V = \frac{1.456}{n} R^{2.3} S^{1.2}$ $S = .009$ (from USGS sheets)
 $Q = AV$

①	H	A	P	R	V	Q	②	H	A	P	R	V	Q
	12	105	105	1	1.4	141		10	105	105	1	1.4	141
	14	375	102.1	2.42	2.58	968		12	376.5	153.2	2.46	2.57	967
	16	722	165.2	4.17	2.63	2065		16	522.5	157.5	4.32	3.71	2073
	18	1120	221	5.5	2.65	4770		18	1012.5	165.5	6.42	4.7	4767
	20	1472	232.5	7.33	2.67	7602		20	1348.5	172.1	7.53	5.53	7472
	22	1715	264.7	8.33	2.67	10274		22	1522.5	175.3	9.57	6.32	10733
③	H	A	P	R	V	Q	④	H	A	P	R	V	Q
	10	610	79.1	7.58	13.6	5764		10	252	5.2	1.85	5.51	2542
	12	730	"	7.72	15.3	1320		12	316	"	6.08	11.74	2730
	14	850	"	10.57	17.3	4875		14	400	"	7.31	13.27	5043
	16	925	"	12.6	19.0	18569		16	444	"	9.54	14.72	1537
	18	120	"	14.1	20.6	22133		18	500	"	9.77	16.11	2152
	20	250	"	15.8	22.7	27713		20	572	"	11.0	17.43	2271
	22	300	"	17.4	23.2	22716		22	636	"	12.5	18.71	11593

D-15

Subject Inspection of non-fed dams

Computation Walcott Dam

Job No. 953-056

Computed by MEP

Checked by

Date 8-8-80

c) Peak Failure Outflow

Peak Failure Outflow = Breach Outflow + Remaining Spillway Flow

$$Q_p = 30,300 + 13,900 \text{ cfs}$$

$$= 44,200 \text{ cfs} \quad \checkmark$$

2. Peak Stage in Immediate Impact Area

Reach #1 800-3000 ft D/s of the dam

Assumed no significant storage within
0-800 ft. downstream of the dam

Road 15 crossing at D/s end of reach

Pre-failure Stage $Q_1 = 20250 \text{ cfs}$ $H = 13.3'$

(Stage-Discharge curve plotted on p. 14)

Reservoir Storage at Time of Failure = 615 acre-ft

(Stage-Storage curve plotted on p. 3)

Volume between pre-failure and post-failure stages:

$$V_1 = 211 - 99 = 112 \text{ acre-ft (x-section following page)}$$

$$V_1 < 1/2 S \quad \therefore \text{O.K.}$$

$$Q_p = 44200 \quad H = 17.8'$$

$$Q_{p2} (\text{Trial}) = Q_p \left(1 - \frac{V_1}{S}\right)$$

$$= 44200 \left(1 - \frac{112}{615}\right)$$

$$= 36000 \text{ cfs} \quad H = 16.4 \quad V = 176 - 99 = 77$$

$$Q_{p2} = Q_p \left(1 - \frac{V_{av}}{S}\right)$$

$$= 44200 \left(1 - \frac{(112 + 77)/2}{615}\right)$$

$$= 37400 \text{ cfs}$$

Post-failure Stage $Q_{p2} = 37400 \text{ cfs}$ $H = 16.8'$

$$\text{Raise in stage} = 16.8 - 13.3 = 3.5'$$

D-14

Subject Inspection of non fed dams

Computation Wolcott Dam

Job No. 953-056

Computed by MEB

Checked by SDM

Date 8-8-80

II Downstream Failure Hazard

1. Peak Failure Flow

a) Breach Outflow

mid-height Elevation $(770.87 - 713)/2 + 713 = 745$

Approx. mid-height length = 120' (from Dam Plan)

$$\therefore \text{Breach Width} = 0.4 \times 120 = 48' \quad W_b$$

Assume surcharge to top of Dam El. 770.87

$$\therefore \text{Height at time of failure } h_b = 52'$$

$$\text{Breach Outflow} = Q_b = \left(\frac{2}{27}\right) W_b \sqrt{g} h_b^{3/2}$$

$$W_b = 48'$$

$$h_b = 52'$$

$$\therefore Q_b \approx 30,300 \text{ cfs}$$

b) Remaining Spillway Discharge

Breach assumed to occur in the spillway section on the right side of the dam.

$$186' - 48' = 138' \text{ of spillway remaining}$$

$$Q = CLH^{3/2} \quad C = 3.8 \quad L = 138 \quad \text{El } 762$$

$$H \quad Q \quad \text{WS El}$$

$$3.87 \quad 13853 \quad 770.87$$

$$Q_s \approx 13,900 \text{ cfs}$$

Subject Inspection of non-federal dams

Computation Walcott Dam Walcott V4.

Job No. _____

Computed by MEB

Checked by SDM

Date 6-29-80

F) Spillway Capacity to Outflow

Spillway Capacity to Top of Dam $C_{100} = 12,672$ cfs

∴ Spillway Capacity is 16% of the full flow at PMF
and 33% of the full flow at 1/2 PMF

5) Summary

a) Peak Inflow $C_{100} = 117,863$ cfs
 $C_{50} = 58,231$ cfs

b) Peak Outflow $C_{100} = 114,800$ cfs
 $C_{50} = 57,000$ cfs

c) Spillway to Top Capacity $C_{100} = 12,672$ cfs
or 16% of C_{100} full flow 33% of C_{50}

Therefore at Full Flood PMF, the dam is overtopped by $\approx 10.6'$
or at 1/2 PMF, the dam is overtopped by $\approx 5.3'$
at 1/4 PMF, the dam is overtopped by $\approx 2.65'$

At 1/2 PMF the dam is overtopped by $\approx 5.3'$ or
to an average height above the spillway crest of
 $14.2'$

Subject Inspection of non-federal dams

Computation Wolcott Dam Wolcott, VT

Job No. 953-05 G

Computed by MEB

Checked by SDM

Date 6-24-80

b) Assumes Normal Pool level at Spillway Crest El. 762 ✓

c) Watershed Area: D.A. = 134.7 mi² ✓

d) Discharge (Q_p) on Various Suctioning Foundation

$$H = 12' \quad V = 180 \text{ cfs} \times 12' = 3240 \text{ cu ft}$$

$$S = 3240 / (52.5 \times 134.7) = .45$$

$$H = 22' \quad V = 180 \text{ cfs} \times 22' = 3960 \text{ cu ft}$$

$$S = 3960 / (52.5 \times 134.7) = .58$$

For Approximate Storage Retention Coefficient
(10) For Probable Max. In Reservoir

$$Q_p = Q_p (1 - S/A) \quad \text{and for } 1/2 \text{ full } Q_p' = Q_p (1 - S/A)$$

$$\text{For } H = 12' \quad Q_p = 115072 \quad Q_p' = 56140$$

$$\text{For } H = 22' \quad Q_p = 114451 \quad Q_p' = 55519$$

On the basis of the above

Using F.E.O. Method Coefficient = "Standard Storage Retention"
Alternate Method

$$Q_p = 112,800 \text{ cfs} \quad S = 19.5' \quad \text{For } Q_p = 112,800$$

$$Q_p' = 57,000 \text{ cfs} \quad S = 14.2' \quad \text{For } Q_p = 112,800$$


JAMES W. SEWELL COMPANY, OLD TOWN, MAINE
Civil and Sanitary Engineers

Sheet 8 of 21

Subject Inspection of non-ferrous dams

Computation Wolcott Dam Wolcott Vt Job No. 953-05 G

Computed by NEA Checked by SDH Date G-24-80



Subject Inspection of non-federal dams

Computation Walcott Dam Walcott Vt

Job No. 953-056

Computed by MEB

Checked by SPK

Date 6-24-80

Rating	Flow	Flow	Flow	Flow	Flow	Flow
11	772.87	1.5	772.87	1.5	772.87	1.5
12	772.87	1.5	772.87	1.5	772.87	1.5
13	772.87	1.5	772.87	1.5	772.87	1.5
14	772.87	1.5	772.87	1.5	772.87	1.5
15	772.87	1.5	772.87	1.5	772.87	1.5
16	772.87	1.5	772.87	1.5	772.87	1.5
17	772.87	1.5	772.87	1.5	772.87	1.5
18	772.87	1.5	772.87	1.5	772.87	1.5
19	772.87	1.5	772.87	1.5	772.87	1.5
20	772.87	1.5	772.87	1.5	772.87	1.5
21	772.87	1.5	772.87	1.5	772.87	1.5
22	772.87	1.5	772.87	1.5	772.87	1.5
23	772.87	1.5	772.87	1.5	772.87	1.5
24	772.87	1.5	772.87	1.5	772.87	1.5
25	772.87	1.5	772.87	1.5	772.87	1.5
26	772.87	1.5	772.87	1.5	772.87	1.5
27	772.87	1.5	772.87	1.5	772.87	1.5
28	772.87	1.5	772.87	1.5	772.87	1.5
29	772.87	1.5	772.87	1.5	772.87	1.5
30	772.87	1.5	772.87	1.5	772.87	1.5
31	772.87	1.5	772.87	1.5	772.87	1.5
32	772.87	1.5	772.87	1.5	772.87	1.5
33	772.87	1.5	772.87	1.5	772.87	1.5
34	772.87	1.5	772.87	1.5	772.87	1.5
35	772.87	1.5	772.87	1.5	772.87	1.5
36	772.87	1.5	772.87	1.5	772.87	1.5
37	772.87	1.5	772.87	1.5	772.87	1.5
38	772.87	1.5	772.87	1.5	772.87	1.5
39	772.87	1.5	772.87	1.5	772.87	1.5
40	772.87	1.5	772.87	1.5	772.87	1.5
41	772.87	1.5	772.87	1.5	772.87	1.5
42	772.87	1.5	772.87	1.5	772.87	1.5
43	772.87	1.5	772.87	1.5	772.87	1.5
44	772.87	1.5	772.87	1.5	772.87	1.5
45	772.87	1.5	772.87	1.5	772.87	1.5
46	772.87	1.5	772.87	1.5	772.87	1.5
47	772.87	1.5	772.87	1.5	772.87	1.5
48	772.87	1.5	772.87	1.5	772.87	1.5
49	772.87	1.5	772.87	1.5	772.87	1.5
50	772.87	1.5	772.87	1.5	772.87	1.5
51	772.87	1.5	772.87	1.5	772.87	1.5
52	772.87	1.5	772.87	1.5	772.87	1.5
53	772.87	1.5	772.87	1.5	772.87	1.5
54	772.87	1.5	772.87	1.5	772.87	1.5
55	772.87	1.5	772.87	1.5	772.87	1.5
56	772.87	1.5	772.87	1.5	772.87	1.5
57	772.87	1.5	772.87	1.5	772.87	1.5
58	772.87	1.5	772.87	1.5	772.87	1.5
59	772.87	1.5	772.87	1.5	772.87	1.5
60	772.87	1.5	772.87	1.5	772.87	1.5
61	772.87	1.5	772.87	1.5	772.87	1.5
62	772.87	1.5	772.87	1.5	772.87	1.5
63	772.87	1.5	772.87	1.5	772.87	1.5
64	772.87	1.5	772.87	1.5	772.87	1.5
65	772.87	1.5	772.87	1.5	772.87	1.5
66	772.87	1.5	772.87	1.5	772.87	1.5
67	772.87	1.5	772.87	1.5	772.87	1.5
68	772.87	1.5	772.87	1.5	772.87	1.5
69	772.87	1.5	772.87	1.5	772.87	1.5
70	772.87	1.5	772.87	1.5	772.87	1.5
71	772.87	1.5	772.87	1.5	772.87	1.5
72	772.87	1.5	772.87	1.5	772.87	1.5
73	772.87	1.5	772.87	1.5	772.87	1.5
74	772.87	1.5	772.87	1.5	772.87	1.5
75	772.87	1.5	772.87	1.5	772.87	1.5
76	772.87	1.5	772.87	1.5	772.87	1.5
77	772.87	1.5	772.87	1.5	772.87	1.5
78	772.87	1.5	772.87	1.5	772.87	1.5
79	772.87	1.5	772.87	1.5	772.87	1.5
80	772.87	1.5	772.87	1.5	772.87	1.5
81	772.87	1.5	772.87	1.5	772.87	1.5
82	772.87	1.5	772.87	1.5	772.87	1.5
83	772.87	1.5	772.87	1.5	772.87	1.5
84	772.87	1.5	772.87	1.5	772.87	1.5
85	772.87	1.5	772.87	1.5	772.87	1.5
86	772.87	1.5	772.87	1.5	772.87	1.5
87	772.87	1.5	772.87	1.5	772.87	1.5
88	772.87	1.5	772.87	1.5	772.87	1.5
89	772.87	1.5	772.87	1.5	772.87	1.5
90	772.87	1.5	772.87	1.5	772.87	1.5
91	772.87	1.5	772.87	1.5	772.87	1.5
92	772.87	1.5	772.87	1.5	772.87	1.5
93	772.87	1.5	772.87	1.5	772.87	1.5
94	772.87	1.5	772.87	1.5	772.87	1.5
95	772.87	1.5	772.87	1.5	772.87	1.5
96	772.87	1.5	772.87	1.5	772.87	1.5
97	772.87	1.5	772.87	1.5	772.87	1.5
98	772.87	1.5	772.87	1.5	772.87	1.5
99	772.87	1.5	772.87	1.5	772.87	1.5
100	772.87	1.5	772.87	1.5	772.87	1.5

Sheet 6 of 21


Computation Walcott Dam Walcott Vt

Job No. 953-056

Computed by MEB

Checked by CDM

Date 6-24-80



Subject Inspection of non-federal dams

Computation Wolcott Dam - Wolcott Vt

Job No. 953-05G

Computed by MEB

Checked by

SDM

Date 8-12-80

Reach 1 Outflow

H_p = Height on time of failure = 43'

V_{p1} = Reach width (page 11) = 48'

$$Q_{p1} = 1.48 \sqrt{g} H_p^{3/2}$$

$$Q_{p1} = 22,800 \text{ cfs} = \text{Peak Failure Outflow}$$

Reach #1 (see pages 12, 13, 14) Wolcott

Veloc. between pre-failure and post-failure stages:

$$V_1 = 116 - 9 = 107 \text{ mph} = 162 \text{ ft/sec} > 5 \text{ ft/sec}$$

$$V_1 < S/2 \therefore \text{Reach O.K.}$$

$$Q_{p2} (\text{trial}) = Q_{p1} (1 - \frac{V_1}{S})$$

$$= 22800 (1 - \frac{107}{225})$$

$$= 13300 \text{ cfs} \quad H = 11.6' \quad V = 63.7 - 54 \text{ mph}$$

$$Q_{p2} = Q_{p1} (1 - \frac{V_1}{S})$$

$$= 22800 (1 - \frac{107 + 54}{225})$$

$$= 15700 \text{ cfs}$$

$$\text{Failure Outflow} = 15700 \text{ cfs} \quad H = 12'$$

Reach #2 (see pages 15, 16, 17) Wolcott

Prefailure Stage = 1'

Veloc. between pre-failure and post-failure stages:

$$V_1 = 187 - 21 = 166 \text{ mph}$$

$$V_1 > S/2 \therefore \text{Select starter Reach}$$

Assume constant x-section, ductile reach = half

$$(Par. 2H) \quad V_1 = 93.5 - 10 = 83.5 \text{ mph}$$

$$Q_{p2} (\text{trial}) = Q_{p1} (1 - \frac{V_1}{S})$$

$$= 15700 (1 - \frac{83.5}{225})$$

$$= 10600 \text{ cfs} \quad H = 13.1' \quad V = 63.3 - 10 = 52.8$$

Subject Inspection of non-federal dam

Computation Wolcott Dam Wolcott Vt

Job No. 953-056

Computed by MEB

Checked by SDM

Date 8-12-80

(Result 2A cont.)

$$Q_{p2} = Q_{p1} \left(1 - \frac{V_{av}}{5}\right)$$

$$= 15700 \left(1 - \frac{(83+52)/12}{2.53}\right)$$

$$\approx 11600 \text{ cfs} \quad H = 12.5'$$

(Result 2E) $V_1 = 71.1 - 10.5 = 60.6$

$$Q_{p2} (\text{at } 12') = Q_{p1} \left(1 - \frac{V_1}{5}\right)$$

$$= 11600 \left(1 - \frac{60.6}{5}\right)$$

$$\approx 9300 \text{ cfs} \quad H = 12' \quad V = 52 - 10.5 = 41.5$$

$$Q_{p2} = Q_{p1} \left(1 - \frac{V_1}{5}\right)$$

$$= 11600 \left(1 - \frac{60.6}{5}\right)$$

$$\approx 9300 \text{ cfs} \quad H = 12.5'$$

Summary - "Low Flow Failure"

a) Peak Failure Outflow = 22,900 cfs
Pre-Failure Flow = 10,711 cfs

b) Approximate stage before failure
Input Areas: Petersville $H = 2.5'$
Wolcott $H = 1.0'$

c) Approximate stage after failure
Input Areas: Petersville $H = 12'$
Wolcott $H = 12.5'$

d) Rise in stage
Input Areas: Petersville $\Delta H = 9.5'$
Wolcott $\Delta H = 2.5'$

PRELIMINARY GUIDANCE
FOR ESTIMATING
MAXIMUM PROBABLE DISCHARGES
IN
PHASE I DAM SAFETY
INVESTIGATIONS

New England Division
Corps of Engineers

March 1978

MAXIMUM PROBABLE FLOOD INFLOWS
NED RESERVOIRS

<u>Project</u>	<u>Q</u> (cfs)	<u>D.A.</u> (sq. mi.)	<u>MPF</u> cfs/sq. mi.
1. Hall Meadow Brook	26,600	17.2	1,546
2. East Branch	15,500	9.25	1,675
3. Thomaston	158,000	97.2	1,625
4. Northfield Brook	9,000	5.7	1,580
5. Black Rock	35,000	20.4	1,715
6. Hancock Brook	20,700	12.0	1,725
7. Hop Brook	26,400	16.4	1,610
8. Tully	47,000	50.0	940
9. Barre Falls	61,000	55.0	1,109
10. Conant Brook	11,900	7.8	1,525
11. Knightville	160,000	162.0	987
12. Littleville	98,000	52.3	1,870
13. Colebrook River	165,000	118.0	1,400
14. Mad River	30,000	18.2	1,650
15. Sucker Brook	6,500	3.43	1,895
16. Union Village	110,000	126.0	873
17. North Hartland	199,000	220.0	904
18. North Springfield	157,000	158.0	994
19. Ball Mountain	190,000	172.0	1,105
20. Townshend	228,000	106.0(278 total)	820
21. Surry Mountain	63,000	100.0	630
22. Otter Brook	45,000	47.0	957
23. Birch Hill	88,500	175.0	505
24. East Brimfield	73,900	67.5	1,095
25. Westville	38,400	99.5(32 net)	1,200
26. West Thompson	85,000	173.5(74 net)	1,150
27. Hodges Village	35,600	31.1	1,145
28. Buffumville	36,500	26.5	1,377
29. Mansfield Hollow	125,000	159.0	786
30. West Hill	26,000	28.0	928
31. Franklin Falls	210,000	1000.0	210
32. Blackwater	66,500	128.0	520
33. Hopkinton	135,000	426.0	316
34. Everett	68,000	64.0	1,062
35. MacDowell	36,300	44.0	825

MAXIMUM PROBABLE FLOWS
BASED ON TWICE THE
STANDARD PROJECT FLOOD
(Flat and Coastal Areas)

<u>River</u>	<u>SPF</u> (cfs)	<u>D.A.</u> (sq. mi.)	<u>MPF</u> (cfs/sq. mi.)
1. Pawtuxet River	19,000	200	190
2. Mill River (R.I.)	8,500	34	500
3. Peters River (R.I.)	3,200	13	490
4. Kettle Brook	8,000	30	530
5. Sudbury River.	11,700	86	270
6. Indian Brook (Hopk.)	1,000	5.9	340
7. Charles River.	6,000	184	65
8. Blackstone River.	43,000	416	200
9. Quinebaug River	55,000	331	330

3000

2500

2000

1500

1000

500

0

M.P.F. IN C.F.S./SQ. MILE

MAXIMUM PROBABLE FLOOD

PEAK FLOW RATES

x5 - NED DAM IDENTIFICATION

⊗ 7' - TWICE SPF AT INDICATED SITES

DEC. 1977

D-27

DRAINAGE AREA IN SQ. MILES

1000

500

100

50


30

20


10

5

2



ESTIMATING EFFECT OF SURCHARGE STORAGE ON MAXIMUM PROBABLE DISCHARGES



STEP 1: Determine Peak Inflow (Q_{p1}) from Guide Curves.

STEP 2: a. Determine Surcharge Height To Pass " Q_{p1} ".

b. Determine Volume of Surcharge ($STOR_1$) In Inches of Runoff.


c. Maximum Probable Flood Runoff In New England equals Approx. 19", Therefore:

$$Q_{p2} = Q_{p1} \times \left(1 - \frac{STOR_1}{19}\right)$$

STEP 3: a. Determine Surcharge Height and " $STOR_2$ " To Pass " Q_{p2} "

b. Average " $STOR_1$ " and " $STOR_2$ " and Determine Average Surcharge and Resulting Peak Outflow " Q_{p3} ".

"RULE OF THUMB" GUIDANCE FOR ESTIMATING DOWNSTREAM DAM FAILURE HYDROGRAPHS



STEP 1: DETERMINE OR ESTIMATE RESERVOIR STORAGE (S) IN AC-FT AT TIME OF FAILURE.

STEP 2: DETERMINE PEAK FAILURE OUTFLOW (Q_{p1}).

$$Q_{p1} = \frac{8}{27} W_b \sqrt{9} Y_0^{3/2}$$

W_b = BREACH WIDTH - SUGGEST VALUE NOT GREATER THAN 40% OF DAM LENGTH ACROSS RIVER AT MID HEIGHT.

Y_0 = TOTAL HEIGHT FROM RIVER BED TO POOL LEVEL AT FAILURE.

STEP 3: USING USGS TOPO OR OTHER DATA, DEVELOP REPRESENTATIVE STAGE-DISCHARGE RATING FOR SELECTED DOWNSTREAM RIVER REACH.

STEP 4: ESTIMATE REACH OUTFLOW (Q_{p2}) USING FOLLOWING ITERATION.

A. APPLY Q_{p1} TO STAGE RATING, DETERMINE STAGE AND ACCOMPANYING VOLUME (V_1) IN REACH IN AC-FT. (NOTE: IF V_1 EXCEEDS $1/2$ OF S, SELECT SHORTER REACH.)

B. DETERMINE TRIAL Q_{p2} .

$$Q_{p2} (\text{TRIAL}) = Q_{p1} \left(1 - \frac{V_1}{S}\right)$$

C. COMPUTE V_2 USING Q_{p2} (TRIAL).

D. AVERAGE V_1 AND V_2 AND COMPUTE Q_{p2} .

$$Q_{p2} = Q_{p1} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$

STEP 5: FOR SUCCEEDING REACHES REPEAT STEPS 3 AND 4.

APRIL 1978

APPENDIX E

INFORMATION AS CONTAINED IN

THE NATIONAL INVENTORY OF DAMS

END

FILMED

8-85

DTIC